

General Environmental Incident Summary

Incident: 619 **Date/Time Notice:** 7/28/2003 0938 **DEM Incident No:**
Responsible Party: J-5 Transport

Date Incident: 7/26/2003 **Time Incident:** 0030 **Duration:** 5 minutes

County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 33 **Qtr:**

Lat: 46.81638 **Long:** -100.78360 **Method:** Derived from TRS

Location Description: Arrowhead Tesoro
220 East Blvd.
Bismarck, ND 58501

Submitted By: Ed "Bud" Kear **Affiliation:**

Address:

City: **State:** **Zip:**

Received By: Gary Berreth

Contact Person: Bud Kear
101 Old Red Trail
Mandan, ND 58554

Distance Nearest Occupied Building: 200 Feet

Type of Incident: tank overflow

Description of Released Contaminant: Gasoline

Volume Spilled: 95.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Jobber was filling underground tank. Tank over-pressured and spewed fuel when delivery hose was disconnected.

Risk Evaluation:

Fire and explosion hazard.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 02 - water

Potential Environmental Impacts:

Approximately 25 gallons of fuel escaped into the city storm sewer.

Action Taken or Planned:

Bismarck Fire Department responded. Floor dry was spread over areas where fuel collected. Approximately 25 gallons of fuel drained into the storm sewer. Remaining fuel evaporated.

Wastes Disposal Location: Bismarck landfill.

Agencies Involved: Local Fire Department

